

Product Change Notice

Issue Date: March 6, 2019

Change Type:


Shipping tray change

Parts Affected:

BCM6303KMLG

Description and Extent of Change:

The shipping tray will be converted from "TX QFN0505 1.0 1435 6 REV.C" to "TX QFN0505 0.85 1435 6 REV.E".



Reasons for Change:

The existing shipping tray may cause the affected parts to stick to the tray.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The device specification will remain the same, which will ensure product electrical performance remains the same. Appropriate electrical characterization and reliability qualification will be performed on representative products to ensure normal parametric distribution, consistent electrical performance, and reliability.



Effective Date of Change:

Product shipments using this change will begin after June 17, 2019. Timing of shipment of the changed shipping tray will vary by part number depending on qualification completion, customer demand, and inventory levels.

Qualification Data:

Not applicable

Please contact your Broadcom Inc. field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.