



<b>Title of Change:</b>	Notification of remove description of UL certification in data sheet and remove UL mark from label on intermediate box and outer box. Intelligent Power Module (IPM) 11 products at ON Semiconductor Vietnam (OSV).
<b>Effective date:</b>	26 Apr 2021
<b>Contact information:</b>	Contact your local ON Semiconductor Sales Office or <a href="mailto:Mitsuru.Oyagi@onsemi.com">Mitsuru.Oyagi@onsemi.com</a>
<b>Type of notification:</b>	This Product Bulletin is for notification purposes only. ON Semiconductor will proceed with implementation of this change upon publication of this Product Bulletin.
<b>Change Category:</b>	ON Semiconductor received official information from EMC supplier to be withdrawn of certain EMC products from UL certification. Below Listed ON Semiconductor products numbers uses one or more of the impacted EMC. Given the UL withdrawn from EMC supplier, ON semiconductor IPM 11 products cannot use UL certification as it UL certification becomes invalid , even though there has been no material change
<b>Change Sub-Category(s):</b>	Datasheet/Product Doc change

**Sites Affected:**

ON Semiconductor Sites	External Foundry/Subcon Sites
ON Semiconductor Vietnam	None

**Description and Purpose:**

Remove description of UL certification in data sheet.

	Before Change Description	After Change Description
Data Sheet	Certification UL1557 (File number: E339285).	Non, Remove UL certification in data sheet

Remove UL mark from label on intermediate box and outer box.

	Before Change Description "RU" symbol	After Change Description "Non-RU" symbol. Remove UL mark from label
Label to intermediate box and outer box	<p>The image shows a label with various fields: (30P) IPN, (Q) QTY, (1T) LOT, (9D) DTE, (1P) MPN, and (S) SERIAL. It also includes 'DIFFUSED IN:US' and 'ASSY IN: TB'. At the bottom, there are logos for Pb, 2LI, e3, RoHS, HF, and the ON Semiconductor logo. The 'RU' symbol is highlighted with a red dashed box.</p>	<p>This image is identical to the previous one, but the 'RU' symbol has been removed from the label.</p>

**List of Affected Standard Parts:**

**Note:** Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the [PCN Customized Portal](#).

STK531U369A-E	STK531U395A-E	STK534UC90A-E
STK531U369C-E	STK531U36AA-E	STK531U394A-E
STK531U394C-E	STK534U342C-E	STK534U362C-E
STK534U363C-E	STK534UC60A-E	

Japanese translation of the notification starts here.  
通知の日本語訳はここから始まります。

*Note: The Japanese version is for reference only. In case of any differences between the English and Japanese version, the English version shall control.*

注：日本語版は参照用です。英語版と日本語版の違いがある場合は、英語版が優先されます。



## 製品速報

文書番号: PB23935X

発行日: 26 Apr 2021

変更件名:	データシートから UL 認証の説明の削除、および中箱と外箱のラベルから UL マークの削除の通知 オン・セミコンダクターベトナム (OSV) のインテリジェントパワーモジュール (IPM) 11 製品		
発効日:	26 Apr 2021		
連絡先情報:	現地のオン・セミコンダクター営業所または < <a href="mailto:Mitsuru.Oyagi@onsemi.com">Mitsuru.Oyagi@onsemi.com</a> > にお問い合わせください。		
通知種別:	本製品速報は通知目的のみのものです。オン・セミコンダクターは本製品速報の発行により本変更を実行します。		
変更カテゴリ:	オン・セミコンダクターは、UL 認証から特定の EMC 製品を取り下げるという正式な通知を EMC サプライヤから受け取りました。以下に記載されているオン・セミコンダクターの製品番号は、影響を受ける一つまたは複数の EMC 製品を使用しています。EMC サプライヤから UL 認証が取り下げられた場合、材料の変更がないとしても、UL 認証が無効になるため、オン・セミコンダクター IPM 11 製品は UL 認証を使用できません。		
変更サブカテゴリ:	データシート/製品資料の変更		
影響を受ける拠点:			
オン・セミコンダクター拠点:	外部製造工場 / 下請業者拠点:		
ON Semiconductor Vietnam		なし	
説明および目的:	データシートから UL 認証の説明の削除。		
	変更前の表記	変更後の表記	
データシート	認証 UL1557 (File number: E339285).	非、データシートから UL 認証の削除	
中箱および外箱のラベル	変更前の表記 "RU" symbol	変更後の表記 "Non-RU" symbol. Remove UL mark from label	
影響を受ける部品の一覧:	注: 標準の部品番号(既製品)のみが部品一覧に記載されます。本 PCN に影響を受けるカスタム 部品は、PCN メールのお客様の特定の PCN の付属文書、または PCN カスタマイズポータルに記載されています。		
	STK531U369A-E	STK531U395A-E	STK534UC90A-E
	STK531U369C-E	STK531U36AA-E	STK531U394A-E
	STK531U394C-E	STK534U342C-E	STK534U362C-E
	STK534U363C-E	STK534UC60A-E	



---

**Appendix A: Changed Products**

---

**PCN#: PB23935X**  
**Issue Date: Apr 25, 2021**

---

---

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier
STK534UC90A-E		STK534UC90A-E		
STK534UC60A-E		STK534UC90A-E		