

**Product Discontinuation Notice**

Asahi Kasei Microdevices Corporation (AKM) announces the discontinuation of products due to the below reason.

Reason A fire that occurred on October 20, 2020 at AKM Fab 2 (Miyazaki, Japan)

Items Please see Appendix 1

Schedule No last time buy (LTB) unless otherwise advised by AKM

For further inquiries, please contact our sales representatives.

Naoya Atsumi
President
AKM Semiconductor, Inc.

226 Airport Parkway Suite 470, San Jose, California 95110
Web inquiry : <http://www.akm.com/akm/jp/support/inquires/>

(Appendix 1)
Affected part numbers

No.	AKM P/N
1	AK09916C
2	AK09940
3	AK09970D
4	AK09970N
5	AK1110AEU50
6	AK1220
7	AK1221
8	AK1222
9	AK1224
10	AK1228
11	AK1291
12	AK1541
13	AK1542A
14	AK1543
15	AK1544
16	AK1547
17	AK1572
18	AK1573
19	AK1573B
20	AK1573C
21	AK1575
22	AK1590
23	AK1594
24	AK1595
25	AK1599V
26	AK2150VA
27	AK2331
28	AK2345
29	AK2346B
30	AK2347B

No.	AKM P/N
31	AK2360A
32	AK2363
33	AK2364
34	AK2400
35	AK2910T
36	AK2920T
37	AK2922H
38	AK2929T
39	AK2970H
40	AK3101
41	AK3102
42	AK3103
43	AK310H
44	AK3713
45	AK4101AVQ
46	AK4103AVF
47	AK4104ET
48	AK4113VF
49	AK4115VQ
50	AK4117VF
51	AK4121AVF
52	AK4122AVQ
53	AK4125VF
54	AK4128AEQ
55	AK4205EN
56	AK4373EN
57	AK4382AVT
58	AK4384ET
59	AK4385ET
60	AK4386ET

(Appendix 1)
Affected part numbers (Continued)

No.	AKM P/N
61	AK4388AET
62	AK4393VM
63	AK4396VF
64	AK4413EQ
65	AK4414EQ
66	AK4420ET
67	AK4430ET
68	AK4462VN
69	AK4468VN
70	AK4480EF
71	AK4482VT
72	AK4490EN
73	AK4490EQ
74	AK4492ECB
75	AK4493EQ
76	AK4495EQ
77	AK4495SEQ
78	AK4497EQ
79	AK4499EQ
80	AK4528VM
81	AK4552VT
82	AK4554VT
83	AK4555VT
84	AK4556VT
85	AK4637EN
86	AK4951EN
87	AK4953AEN
88	AK4958EG
89	AK5355VT
90	AK5357ET

No.	AKM P/N
91	AK5357VT
92	AK5358AET
93	AK5358BET
94	AK5374EN
95	AK5381ET
96	AK5384VF
97	AK5385BVF
98	AK5386VT
99	AK5388AEQ
100	AK5388EQ
101	AK5397EQ
102	AK5536VN
103	AK5556VN
104	AK5576EN
105	AK5701VN
106	AK5703EN
107	AK5730VQ
108	AK7451
109	AK7452
110	AK7454
111	AK7742EQ
112	AK8142
113	AK8160B2
114	AK8172A
115	AK8185A
116	AK8771
117	AK8772
118	AK8775
119	AK8776
120	AK8777B

(Appendix 1)
Affected part numbers (Continued)

No.	AKM P/N
121	AK8778B
122	AK8788A
123	AK8789
124	AK8817VQ
125	AK8826VN
126	AK8858VQ
127	AK8963C
128	AK9232NK
129	AK9233NK
130	AK9234NK
131	AK9240NK
132	AK9242NK
133	AK9255ANK
134	AK9255NK
135	AK9256ANK
136	AK9256NK
137	AK9750
138	AK9752AE
139	AK9753AE
140	AK9754AE
141	AP1012A
142	AP1017AEN
143	AP1021AEN
144	AP1025BEN
145	AP1035AER
146	AP1037AER
147	AP1040AEN
148	AP1150ADS18
149	AP1150ADS33
150	AP1150ADS50

No.	AKM P/N
151	AP1151ADS
152	AP1152ADU18
153	AP1152ADU33
154	AP1152ADU50
155	AP1153ADS18
156	AP1153ADS33
157	AP1153ADS50
158	AP1154ADL18
159	AP1154ADL33
160	AP1154ADL50
161	AP1155ADL
162	AP1156ADS15
163	AP1158ADS
164	AP1159ADS09
165	AP1159ADS12
166	AP4405AENFE
167	AP4405AENJG
168	AP4405AENMH
169	AP4405AENTS
170	AP4405AENU2
171	AP4410AECHJ
172	AP4410BECHN
173	AP4410BECSJ
174	CQ2063
175	CQ2064
176	CQ2065
177	CQ206A
178	CQ206B
179	CQ2092
180	CQ209A

(Appendix 1)
Affected part numbers (Continued)

No.	AKM P/N
181	CQ209B
182	CQ209D
183	CZ3813
184	CZ3814
185	CZ3815
186	EM1011
187	EM1711
188	EM1712
189	EM1771
190	EM1781
191	EM1791
192	EM3242
193	EM6781
194	EW6672