



PRODUCT DISCONTINUATION NOTICE

PDN No.: USA2017- 002

IXYS PRODUCT TYPE:	TYPE:	RECOMMEND REPLACEMENT:
TRENCH MOSFET	IXTY12N06T, IXTY12N06T TRL	CONTACT FACTORY

REASON FOR DISCONTINUATION: OBSOLETE TECHNOLOGY AND LACK OF DEMAND FOR PRODUCT

LAST TIME ORDER DATE: **CONTACT THE FACTORY**

LAST TIME DELIVERY DATE: **CONTACT THE FACTORY**

INTERNAL REFERENCE:

In case of any question, please contact: Sudhir Kommineni, IXYS Corp. Milpitas, CA e-mail: S.Kommineni@ixys.net

INITIATOR: GORDON ROSETE TITLE/FUNCTION: DEPT. HEAD QA DATE: 03/22/2017 E-MAIL: G.ROSETE@IXYS.NET

CUSTOMER RESPONSE:

(PLEASE FILL IN AND RETURN BY E-MAIL, FAX OR MAIL WITHIN 4 WEEKS)

for further questions/ information
please comment

Company: _____
Name & Position _____
Phone / Fax No: _____

COMMENTS: _____

